

Fiber optic communication interrupted at the substation



Overview

The most common reason for interrupted fiber optic service is fiber optic cable cuts. A TO experienced an unplanned interruption on its “Path A” (fiber optic) that impacted several communication circuits due to previously rerouted circuits during an ongoing planned outage on “Path B” (microwave). As a result, select relay communications were affected in addition to the monitoring. Fiber optic troubleshooting is an essential skill for network administrators, technicians, and engineers responsible for maintaining and repairing fiber optic systems. Fiber offers several advantages: • Higher bandwidth that supports higher data rates over longer distances: A typical bandwidth-distance product for multimode fiber is 500 MHz/km, so a 500-meter cable can transmit 1 GHz, while. Electrical substations, provide an efficient means to deliver power to end users. Reliable communication is key to providing the most efficient means possible.



Article Content

Mar 15, 2026

Schematics and docs needed for communication ...

Figure 2 shows a detail from a larger, more complex conceptual block diagram for a complete substation automation system without the IRIG-B ...

Apr 11, 2026

Communications Equipment Used in Substations

Explore essential communication equipment for substations, including RTUs, PLCs, fiber optic and wireless solutions. Learn about key protocols like DNP3, IEC 61850, and Modbus for ...

Aug 17, 2025

FOA Guide

Fiber Optic Network Restoration These are guidelines for designers and users of fiber optic communications networks as well as contractors and techs who install, operate and maintain them. ...

Mar 06, 2026

Case Study: IEC 61850 as Automation Standard for New ...

This paper discusses best practices and lessons learned during the execution of several projects developed for new substations using IEC 61850 as a communications suite.

Nov 18, 2025

Guidelines for the Design of Critical Communications Circuits

Since most communication equipment is not substation hardened, it is susceptible to electrical, electro-magnetic, and associated noise. Therefore, special precautions must be taken when designing, ...

Jul 23, 2026

OPTICAL FIBER IN THE ELECTRICAL SUBSTATION

Tapping fiber optic communication technology is incredibly difficult, and because attempts to tap fiber cables will likely result in breaking the glass fibers, potential hacks can be quickly and easily discovered.

Feb 04, 2026

Lesson Learned

As an immediate correction to the Path A interruption, a spare fiber optics cable was temporarily utilized to bypass the break and restore failed data communications.

Jun 20, 2026

Lessons Learned from a 400kV Busbar Misoperation Utilizing the ...

With the advent of Intelligent Electronic Devices (IEDs), data sharing between protective relays and control centers has become possible by using Ethernet and fiber optic cables. This has reduced the ...

Oct 28, 2025

Fiber Optic Troubleshooting: Expert Guide for Common ...

Troubleshoot fiber optic issues like a pro with our expert guide. Resolve common problems and ensure seamless connectivity.

Jul 31, 2025

Fiber Optic Cable Cuts: Most Common Causes & How To Combat Them

The most common reason for interrupted fiber optic service is fiber optic cable cuts. And the list of causes of causes for fiber cuts, believe it or not, is a long one. In this article, we've rounded up the ...

Nov 15, 2025

Schematics and docs needed for communication systems of substation ...

Figure 2 shows a detail from a larger, more complex conceptual block diagram for a complete substation automation system without the IRIG-B distribution shown. This drawing was ...

Contact Us

For more information, pricing, or custom solutions, please contact us:

Website: <https://ntmmgroup.co.za>

Email: sales@ntmmgroup.co.za

Phone: +27 82 471 2596

Address: Unit 7, Optic Park, 24 High-Tech Lane, Century City, Cape Town,
7441, South Africa

This document is for informational purposes only. Specifications subject to
change without notice.

